ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0146, I0163, W0165, W0155, W0167, W0144, I0142, W

Street Name
NA, 3rd Crs, 1st Crs, 2nd Crs

Significant Landmark
Maheshwara Temple to Ramachandrapura Circle

Segment No.
10/C-W0146/S035516

Total Length (m)
193.19

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	130.30	77.551645	13.062618	77.551077	13.061662	I0163	W0699
2	62.89	77.551377	13.062174	77.551947	13.062068	W0065	I0163

Work Details

History of Road / Lane / Circles

Name of the Work
Asphalting to Road from Maheshwara Temple to Ramachandrapura Circle in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1500000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Asphalting to Road from Maheshwara Temple to Ramachandrapura Circle in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
010-16-000015

Work Order No.
BBMP/EE/BTP/WO/310/2014-15

Work Order Date
16/02/2016

Period of Extention
60 DAYS

Defect Liability Period From
16/02/2016

Defect Liability Period To
15/02/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
VINOD KUMAR

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

9886368484

Field Inspection Details

Number of Trees	Any Other Information	Name
3		MADHAVA RAO
Date of Inspection	**Remarks**	
03/12/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0146, I0163, W0165, W0155,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	VASU K M	03/12/2016	02/01/2017	COMPLETED
AEE	SHIVAKUMAR	03/12/2016	02/01/2017	COMPLETED
AE	MADHAV RAO	03/12/2016	02/01/2017	COMPLETED
AE	MADHAV RAO	03/12/2016	02/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0146, I0163, W0165, W0155,